

报告编号	结论	报告日期	图片	备注
DAJC-7F10294-2022	合格	2022-06-23		

DAJC-7F10295-2022

合格

2022-07-09



经度: 117.584720

纬度: 36.225163

地址: 山东省济南市莱芜区莱芜市鑫淼建筑机械租赁有限公司(西1门)

时间: 2022-06-23 16:42:10

海拔: 177.9米

天气: 29°C 西北风 晴

备注: 长按水印编辑备注

DAJC-7F10296-2022

合格

2022-07-09



DAJC-7F10297-2022

合格

2022-07-09



DAJC-7F10298-2022

合格

2022-07-09



经度: 117.598132

纬度: 36.202631

地址: 山东省济南市莱芜区莱城

大道518号博文家政培训学校

时间: 2022-06-23 14:21:07

海拔: 202.5米

天气: ☁️ 30 - 34°C 西北风

备注: 长按水印编辑备注

DAJC-7F10299-2022

合格

2022-07-09



经度：网络获取失败
纬度：网络获取失败
地址：正在加载中...
时间：网络获取失败
海拔：网络获取失败
天气：网络获取失败
备注：长按水印编辑备注

DAJC-7F12101-2022

合格

2022-06-24



DAJC-7F13471-2022

合格

2022-06-24



经度：网络获取失败
纬度：网络获取失败
地址：正在加载中...
时间：网络获取失败
海拔：网络获取失败
天气：网络获取失败

DAJC-7F13472-2022

合格

2022-06-24



经度：网络获取失败
纬度：网络获取失败
地址：正在加载中...
时间：网络获取失败
海拔：网络获取失败
天气：网络获取失败

DAJC-7F13473-2022

合格

2022-06-24



经度: 网络获取失败
纬度: 网络获取失败
地址: 正在加载中
时间: 网络获取失败
海拔: 网络获取失败
天气: 网络获取失败

DAJC-7F32146-2022

合格

2022-07-09



DAJC-7F32147-2022

合格

2022-07-09



经度: 111.693977

纬度: 40.832364

时间: 2022-07-09 09:34:45

备注: 亨泰矿业

DAJC-7F32148-2022

合格

2022-07-09



DAJC-7F49009-2022

合格

2022-07-09



DAJC-7F50042-2022

合格

2022-07-09



经度: 111.694037

纬度: 40.832239

时间: 2022-07-09 13:14:49

备注: 亨泰矿业

DAJC-7F88014-2022

合格


2022-07-09



DAJC-7F89053-2022

合格

2022-07-09




经度: 111.693998

纬度: 40.832203

时间: 2022-07-09 11:08:42

备注: 亨泰矿业

DAJC-7F93011-2022	合格	2022-07-09	 <p>经度：111.693946 纬度：40.832562 时间：2022-07-09 09:19:47 备注：亨泰矿业</p>	
DAJC-7F38687-2022	合格	2022-7-5	/	
DAJC-7F47211~213-2022	合格	2022-7-8	/	

DAJC-128013-2022

合格

2022-05-15



DAJC-128014-2022

合格

2022-05-15



DAJC-128015-2022

合格

2022-05-15



DAJC-128016-2022

合格

2022-05-15



DAJC-128017-2022

合格

2022-05-15



DAJC-128018-2022

合格


2022-05-15



DAJC-128019-2022

合格

2022-05-15



DAJC-128020-2022

合格

2022-05-15

