

报告编号	结论	报告日期	图片
DAJC-107032-2022	合格	2022-05-23	 <p>现场拍照</p> <p>经度: 117.847533          纬度: 34.850461          地址: 山东省临沂市兰陵县光明路爱贤回民小学</p> <p>经度: 117.841021          纬度: 34.851135          地址: 山东省临沂市兰陵县光明路临矿集团会宝岭铁矿公司          时间: 2022-05-10 07:48:32          海拔: 88.7米</p>

DAJC-107058-2022

合格

2022-08-10



# 宋家庄矿区主井

经度: 121.500543

纬度: 37.024031

地址: 山东省威海市乳山市207省道  
宋家庄南(公交站)

DAJC-107059-2022

合格

2022-08-10

经度: 网络获取失败

纬度: 网络获取失败

地址: 正和和静中...



经度: 121.636571  
纬度: 37.114010  
地址: 山东省威海市乳山市206省

DAJC-107060-2022

合格

2022-08-10



经度: 网络获取失败  
纬度: 网络获取失败

DAJC-107061-2022

合格

2022-08-10



DAJC-108161-2022

合格

2022-08-10



DAJC-108162-2022

合格

2022-08-10



DAJC-108177-2022

合格

2022-08-10





DAJC-108178-2022

合格

2022-08-10



DAJC-108178-2022

合格

2022-08-10



经度：网络获取失败  
纬度：网络获取失败



经度：网络获取失败  
纬度：网络获取失败  
地址：正在加载中...

DAJC-108179-2022

合格

2022-08-10



DAJC-108180-2022

合格

2022-08-10





经度: 121.564897  
纬度: 37.042968  
地址: 山东省威海市乳山市308国

DAJC-108181-2022

合格

2022-08-10



经度: 119.935181  
纬度: 37.188203  
地址: 网络获取失败  
时间: 网络获取失败

DAJC-109039-2022

合格

2022-08-10



# 宋家庄矿区主井

经度: 121.500543

纬度: 37.024031

地址: 山东省威海市乳山市207省道  
宋家庄南(公交站)

DAJC-109040-2022

合格

2022-08-10



经度: 网络获取失败

纬度: 网络获取失败

地址: 正在加载中...

DAJC-109041-2022

合格

2022-08-10





DAJC-109042-2022

合格

2022-08-10

